

State Route (SR) / US Route or Road Name and Description:

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

Are corrective actions required by this inspection report (Y/N):

DATE: 6.9.1/

	Wolf River Blvd.				YES		
County(ies):	TDOT PIN:	NPDES Permit (NOC)	#:	Number of New	Number of Recurring	Number of New	Number of Un-Corrected
Shelby	101615	TNR153299)	Corrective Actions:	Corrective Actions:	Sediment Releases:	Sediment Releases:
TDOT Construction No.: 7994-1535-54	TDOT Contract No.:	Contractor: Acuff Enterprises Inc.		5	3	0	\circ
I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as recorded in the table above. I am aware that there are significant penalties for				t EPSC Inspector and 1 Gerald "Jerry" S		Signature:	Stamper
				TEPSC Inspector and Tom Acuff	ř	Signature: Signature:	cuff
submitting false information, including the possibility of fine and impresonment for knowing violations.			(print or type): Michael Rebick				20

TDOT EPSC Inspection Weekly Rainfall Data Log

		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or (YES)
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, explain and initial:
	Sunday				N/A	N/A	N/A	N/A		
5/6/11	Monday	10	0	0	N/A	N/A	N/A	N/A		an process of correction
	Tuesday				N/A	N/A	N/A	N/A		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	Wednesday				N/A	N/A	N/A	N/A		actions
19/11	Thursday	30	0	0	N/A	N/A	N/A	N/A		
40/11	Friday	30		A-22 = 919423015	N/A	N/A	N/A	N/A		
11/11	Saturday	10			N/A	N/A	N/A	N/A	•	
/12/11	Sunday	30			N/A	N/A	N/A	N/A		
112/11	Monday	0			N/A	N/A	N/A	N/A		
			2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	***************************************			*		*****	(Additional pages may be attached, if needed)

0	D	^
Predicted	Precipitation	SOURCE.
rodioted	recipitation	OCHICC.

	AND COMPANY DATES		
WWW	111001	hor	2000

16	O	THE	(S)	
OMENTS	AGR	icui	TURE	
1/2	(1796	30	Ž.

01-1-1110	D1-	D I	A Parisa and	1
State/US	Route	or Road	Name:	1

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	6/9/2011
	1-0 miles (10 mi

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	6/3/2011		22	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	6/9/2011	T = 3-25-11	16,33,35	S	Area has been corrected. See photo
1B	1	22+00	RT	6/9/2011	T= 3-25-11	16,24,33,35	S	Area has been corrected. See photo
1C	1	21+00	LT	6/9/2011	T = 3-25-11	10,12,16,33,35	1	Area needs to be stable. See photo
2A	1	33+50	RT	3/25/2011	T = 3-25-11	16,33	FM	The damaged SFB will need to repaired before work begins.
2B	1	35+50	RT	3/25/2011	T = 3-25-11	16,33	S	STABLE (NO ACTION NEEDED)
3	1	34+50	LT				S	The area has not been disturbed.
4	1	40+00	RT				S	The area has not been disturbed.
5A	1	49+00	RT				S	The area has not been disturbed.
5B	1	50+00	RT				S	The area has not been disturbed.

EROSION AND SEDIMENT CONTROL MEASURE CODES

	EROSION AND SEDIMENT CONTROL MEASURE CODES						
1	Temporary Silt Fence / Filter Barrier	15		29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dessipater	35	Sediment Tube	W	Too Wet to Work Condidtions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, reprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42		Other (O#3):	

Y .	S
到: 3);	
<i>\$ </i>	

State/US	Route	or Road	Name
----------	-------	---------	------

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	6/9/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT				S	The area has not been disturbed.
6	1	56+00	LT			- 24	S	The area has not been disturbed.
7	1	60+00	RT				S	The area has not been disturbed.
8A	1	73+00	RT				S	The area has not been disturbed.
8B	2	75+50	RT				S	The area has not been disturbed.
8C	1	71+00	LT				S	The area has not been disturbed.
8D	2	75+50	LT		- (S	The area has not been disturbed.
8E	1	71+50	LT				S	The area has not been disturbed.
9A	2	80+00	RT	6/9/2011	T = 5-31-11	16,35	S	Stable (No action needed)
9B	2	80+00	LT	6/9/2011	T = 6-6-11	16,35	S	Stable (No action needed)

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 1 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily М Maintenance 2 Temporary Diversion Berm or Ditch 16 **Temporary Mulch** 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 5 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions 22 8 Sand Bags Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release **Temporary Stream Crossing** 10 Temp Sediment Filter Bag / Dewatering 24 38 Berm (soil, reprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Machined Rip Rap 26 12 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade 42 Other (O#3):

CONDITION CODES

State/US Route or Roa

ate/US Route or Road Name:	Wolf River Blvd.

TDOT Construction N	ο.

79954-353	

TDOT Contract No.:	
--------------------	--

Date	6/9/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stablilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	6/9/2011	T = 5-31-11	16	S	Stable (No action needed)
10A	2	85+00	RT	6/9/2011	T = 5-31-11	16,24	S	Currently stable, Monitoring BMP's
10B	2	85+00	RT	6/9/2011	T = 5-31-11	16,24,35	S	Currently stable, Monitoring BMP's
10C	2	85+50	LT	6/9/2011	T = 5-31-11	16,35	S	Stable (No action needed)
10D	2	84+50	LT	6/9/2011	T = 5-31-11	16,35	S	Stable (No action needed)
11A	2	92+50	RT	6/9/2011	T = 5-31-11	16,24,35	S	Stable (No action needed)
11B	2	92+50	LT	6/9/2011	T = 5-31-11	10,16,35	S	Currently stable, Monitoring BMP's
11C	2	92+00	LT	6/9/2011	T = 5-31-11	16,35	S	Stable (No action needed)
	1	11+28	LT	6/9/2011	T = 6-3-11	19,35	S	Stable (No action needed)
	1	13+40	RT	6/9/2011		23,29,30	C,M	Make corrections to construction exit to function properly and to control <u>DUST</u> . See photo.
	1	107+75	CL	6/9/2011		23,29,30	C,M	Make corrections to construction exit to function properly and to control <u>DUST</u> . See photo.

EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITION CODES Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch Temporary Mulch 30 Haul Roads Dampened for Dust Control U 16 Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 33 C 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures Straw Bale Check 7 21 Riprap Energy / Velocity Dessipater 35 Sediment Tube W Too Wet to Work Condidtions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, reprap, rock) FS Final Stabilized 10 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S 11 Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Freserve ivalural resource / Duller Zone naul Rudu ULIET (U#Z) 14 Permanent Seeding with Mulch or Sod 28 42 Other (O#3): Mineral Aggregate Base on Subgrade



Outfall 1A Sta. 21+50 RT Area has been corrected.



Outfall 1B Sta. 22+00 RT Area has been corrected.



Outfall 1C Sta. 21+00 LT Area needs to be stabilized. (I)



Sta. 13+40 RT Construction exit needs to stabilized and to control <u>DUST</u>. (C,M)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Sta. 107+75 LT
Corrective actions and maintenance are required daily to properly control *DUST*. (C,M)



Dress and stabilize construction exit daily to function properly and to control <u>DUST</u>. (C,M)



Sta. 107+75 CL
Corrective actions have been corrected, but future maintenance is required daily.
(FM)



Sta. 10/+/3 K1
Corrective actions have been corrected, but future maintenance is required daily.

(FM)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138